

NOVA 2 Pound Digital Scale

Model # P21PL-M



www.escali.com

INITIAL SETUP

1. Insert batteries into the battery compartment located beneath the scale.
2. Place the stainless steel plate on the scale.

WEIGHT MEASUREMENTS

1. Press the **On/Tare/Off** button to turn on the scale.
2. Press the **g/oz** button to change units of measure.
3. Place an item on the scale in the center of the platform.

TARE (ADD & WEIGH)

Ignore the weight of a container:

1. Turn on the scale and place the container on the platform.
2. Press the **On/Tare/Off** button, and zero weight will display.
3. Add items into the container to be weighed.

Find the individual weight of multiple items in one container:

1. Press **On/Tare/Off** to reset the scale back to zero weight.
2. Add additional items to be weighed.
3. Repeat steps 1-2 for additional items.

Reset the scale back to zero weight:

1. If nothing is on the scale and it does not read zero weight, press the **On/Tare/Off** button to reset the scale back to zero weight.

Attention! When using the tare feature, the weight of the container can not exceed 2 pounds or 1 kilogram.

AUTOMATIC SHUT-OFF

The scale will turn off after 5 minutes of inactivity to save battery.

OVERRIDE AUTOMATIC SHUT-OFF

A switch to over-ride the auto shut-off is located in the battery compartment. Turn the switch "**ON**" to over-ride the auto shut-off feature.

OPTIONAL 9-VOLT WALL ADAPTER AVAILABLE

The adapter is available at www.escali.com.

PROPER USE & CARE

- Use and stow the scale at room temperature.
- Use on a flat, level and stable surface.
- The scale is an instrument of precision. Do not submit the scale to shaking, excessive vibration, or other rough treatment.
- The display may be affected by electromagnetic disturbances such as radios, microwaves or cell phones. If such disturbances occur, remove the source of the disturbance & restart the scale.
- Disassembling or tampering with the scale voids the warranty.
- Clean the scale with dish soap and a damp cloth.
- Do not submerge in liquid. The scale is not waterproof.

WARNING MESSAGES

- EEEE Overload warning.
out2 Load cell is damaged or needs recalibration.
unst The scale is in an unstable environment.
 Low battery warning.

PRODUCT SPECIFICATIONS

Model: P21PL-M

Capacity: 2 lb. (1,000 g.)

Graduation: 0.05 oz. (0.5 g.)

Product Dimensions: 5.75" x 8.25" x 1.5"

Platform Dimensions: 5.75" x 5.75"

Power Source: 2 - AA batteries (included),
Optional 9-volt wall adapter (not included).

Automatic shut-off: 5 minutes

NSF Certified

ESCALI CORPORATION

3203 Corporate Center Drive, Suite 150
Burnsville, MN 55306
USA

PRODUCT SUPPORT

24/7 Online support: <https://escali.zendesk.com>

Email support: feedback@escali.com

Phone support: 1-800-467-6408



2 YEAR PROFESSIONAL GUARANTEE

This scale is guaranteed to be free of defects in materials and workmanship. For more details visit: www.escali.com/warranties

Escali's liability is limited to two (2) times the cost of the product.

© Escali Corp., Minneapolis, MN, USA. All rights reserved. Escali, the Escali logo and other Escali marks are owned by Escali Corp. and may be registered.